



## ČISTÍCÍ KOTOUČE



Pro čištění koutů a svarů (nerezový mat.) a odstraňování barev, oxidací.

### Čistící kotouče na stopce z mat. Clean & Strip (C&S)

- nejagresivnější verze materiálů Scotch-Brite

	TYP	Obj.č.	φ x šířka x otvor [mm]	Stopka [mm]	Max.otáčky [min <sup>-1</sup> ]	
	FVOK 75/13	907 055	75x13	6	8 000	5
	FVOK 75/26	907 056	75x26	6	8 000	5
	FVOK 100/13	907 057	100x13	6	6 000	5
	FVOK 100/26	907 058	100x26	6	6 000	5
	FVOK 150/13	907 059	150x13	6	4 000	5
	FVOK 150/26	907 060	150x26	6	4 000	5

### Čistící kotouče s otvorem z mat. Clean & Strip (C&S)

	TYP	Obj.č.	φ x šířka x otvor [mm]		Max.otáčky [min <sup>-1</sup> ]	
	FVOS 100/13	903 462	100x13x14		8 000	5
	FVOS 150/13	903 463	150x13x14		4 000	5
	FVOS 200/13	906 362	200x13x14		3 000	5

### Nosič

	TYP	Obj.č.	φ x šířka x otvor [mm]		Max.otáčky [min <sup>-1</sup> ]	
	FD 6-14	904 705	100, 150x13x14	6	8 000	1