


LSA 70

Technical drawing of a bolt head in cross-section. The drawing shows a hexagonal bolt head with a central hole. The outer edge is hexagonal, and the inner hole is circular. A dimension line at the bottom indicates a diameter of 20.



LSA 81

Technical drawing of a circular part, likely a cross-section of a shaft or a similar component. The drawing shows concentric circles representing different layers or features. A dimension line at the bottom indicates a diameter of 19.



RUPET
international



Po cca 300-400 hodinách (alespoň jednou za rok) vyčistěte obal motoru a zkontrolujte opotřebování lamel.

Typ	Obj.č.	Otáčky	Kleština	Spotřeba vzduchu při chodu naprázdno	Hmotnost
		min ⁻¹	ø		kg
LSA 70	112 044 01	80 000	3mm	0,220 m³/min	0,160
LSA 81	057 070 01	80 000	3mm	0,200 m³/min	0,310

	Příkon	Ventil	Přívodní hadice vzduchu
LSA 70	75 W	Otočný ventil	–
LSA 81 –	75 W	Otočný ventil	5–6 mm vnitřní ø

1 x Kleština, ø 3mm 1 x Sada klíčů **LSA 81 ▶ Přívodní a výfuková hadice s koncovkou**

LSA 81 Set	Obj.č.	112 213 02
------------	--------	------------



Přímá bruska LSA 81 + 6 tvrdokovových fréz různých tvarů se souvislým břitem.

		Typ	Průměr kleštiny	Obj.č.	Hmotnost
					kg
	Kleštiny	SPZ	ø 3mm	014 913 02	0,008
		SPZ	1/8" ø (3,175 mm)	014 913 03	0,008
		SPZ	3/32" ø (2,380 mm)	014 913 01	0,008
	Klíč	SW 8	–	037 857 06	0,020