

Pneumatická priama brúska LSA 79

110 W
 Otáčky
 77 000



Nie ste si istí, čo všetko môžete do brúsky upnúť?

Pozrite sa na náš sortiment.


Dostupné brusivo

Modré brusivo




Používané predovšetkým pri výrobe foriem a je určené pre veľmi tvrdé materiály.


TYP	A 0206 BS	A 0306 BS	A 0406 BS	A 0510 BS	A 0610 BS	A 0808 BS
d x l [mm]	2 x 6	3 x 6	4 x 6	5 x 10	6 x 10	8 x 8
D / L [mm]	3/38	3/38	3/38	3/38	3/38	3/38
Zrno	K-120	K-120	K-120	K-120	K-120	K-120
Obj. č.	910 038	910 039	910 040	910 041	910 042	910 043



TYP	F 0303 BS	F 0505 BS	F 0606 BS
d x l [mm]	3 x 3	5 x 5	6 x 6
D / L [mm]	3/38	3/38	3/38
Zrno	K-120	K-120	K-120
Obj. č.	910 044	910 045	910 046



TYP	K 0610 BS	K 0306 BS
d x l [mm]	6 x 10	3 x 6
D / L [mm]	3/38	3/38
Zrno	K-120	K-120
Obj. č.	910 047	910 048



Do \varnothing 10 maximálne otáčky 80 000/min.

Technické frézy – stopka 3 mm








Ponúkame rôzne tvary fréz. Môžete si vybrať z dvoch druhov zubov

- ZUB 6 - NK dvojité brit
- ZUB 3 - N súvislý brit

Tvary:

- A valcové, B valcové s čelným britom, C valcové s rádiusom, D guľové, E elipsovité, F stromčekové s rádiusom, G stromčekové so špičkou, H plamienkové, L kužeľové s rádiusom, M kužeľové, N obrátený kužeľ



Keramické brusivo

Ideálne pre brúsenie hrán, odhrotovanie a odstraňovanie zvarov.



VALEC A



TYP	A 0205 MK	A 0205 EK	A 0205 EW	A 0306 V	A 0408 V	A 0510 V		A 0613 V		A 0810 V	A 0816 V
d x l [mm]	2 x 5	2 x 5	2 x 5	3 x 6	4 x 8	5 x 10		6 x 13		8 x 10	8 x 16
D / L [mm]	3/35	3/35	3/35	3/36	3/38	3/42		3/43		3/40	3/47
Zrno	K-100	K-100	K-100	jemné	jemné	hrubé	jemné	hrubé	jemné	jemné	jemné
Obj. č.	910 118	910 119	910 120	900 274	900 275	900 290	900 276	900 291	900 277	900 278	900 279
	str. tvrdé	tvrdé	veľmi tvrdé								

VALEC S RÁDIUSOM C



TYP	C 0306 V	C 0510 V
d x l [mm]	3 x 6	5 x 10
D / L [mm]	3/37	3/48
Zrno	jemné	jemné
Obj. č.	900 281	900 282

GULE F



TYP	F 0303 V	F 0505 V
d x l [mm]	3 x 3	5 x 5
D / L [mm]	3/34	3/34
Zrno	jemné	jemné
Obj. č.	900 286	900 287

VALEC SO ŠPIČKOU K

TYP	K 0306 V	K 0510 V		K 0816 V	
d x l [mm]	3 x 6	5 x 10		8 x 16	
D / L [mm]	3/35	3/41		3/46	
Zrno	jemné	hrubé	jemné	hrubé	jemné
Obj. č.	900 283	900 296	900 284	900 297	900 285

